Figure 1

Arbor
5 Return
1 Turn OD
Z Zero
3 Turn
Groove
2 Move to Zero
4 Back to Zero